	AWL paymer	nt due:	December	
Date of Award:	12/1/2025	Lot Number:	10	
Name: Davis			Buyer	
Membership Price (222)			2,672.52	
Infrastructure Initial Payment (425)			200.00	
Lot Improvement Value (222)			16,915.71	
Sub-Total:			19,788.23	
	Amount	Paid (Y or N)	Prorated Amount	
AWL Deposit (111)	500.00	Υ	-500.00	
Maintenance Fee: (423)	1,557.00		129.75	
County & School Taxes (222)	88.40		-81.03	
Membership Transfer Fee (422)			200.00	
Value of Propane in Tank: (222)			0.00	
Grand Totals:	The manufacture and the state of the state o		19,536.9	

11.24.2025 Cg X SG

## ALAMO AREA SKP CO-OP LOT SALE WORK SHEET

(Page 1 of 2) EVALUATION FORM

SELLER:	Davis	LOT #: _ <i></i>	DATE: 12 NOV, 2025
1.	VALUE CARRIED FORWARD FROM	ARCHIVE: A \$ /2,7/0.2/	
2.	NEW IMPROVEMENTS:  i. SHED  ii. CONCRETE  iii. GRAVEL  iv. FENCE  v. PROPANE TANK  vi. INSTALLATION  OR LABOR  vii. LANDSCAPING  viii. OTHER  TOTAL	\$ 3,323,45 \$ \$ \$ 871,78 \$ \$ 10,27 \$ 4,205,50	
3.	ADJUSTMENTS  TOTAL ADJ.	\$ \$ \$	
4.	REMOVALS  i. SHED  ii. TREES/SHRUBS  iii. OTHER  TOTAL	\$\$ \$\$ \$	
5.	LOT IMPROVEMENT ~ SUBTOTAL	B\$ 4,205,50	(Lines 2 + 3 + 4)
6.	TOTAL LOT IMPROVEMENT VALUE	cs 16,915,71	(Lines 1 + 5)
7.	PROPANE TANK SIZE:	GALLONS  O X O 1 = \$ (Current Price per Gallon)	(Propane Value)
NOTES: _			
EVALUA	CONFER BARNES	Acto Seath	the SITTHW

**Evaluation** 

LOT # 10

November 19, 2025

This evaluation was done by volunteers of the Lonestar Corral Co-Op Evaluations Committee.

This lot is located on the East end of the Co-Op on the East side of Private Road 5247 and faces West. Co-Op perimeter fence bounds CR 5229 to the East of the lot. The lot has a very roomy feel.

The lot has a 12 x 24 shed consisting of a main room and a utility room, with an 8' x 24' enclosed porch. Shed has a new self-storing storm door. Shed interior is painted sheetrock with paneled wainscotting. The lot has a 150 Gal propane tank with service for an RV. Shed is conventionally framed on a concrete slab with fiberglass shingle roof. Lot has an 18'x49' concrete parking pad.

Main room measures approx. 11'x17' Wall to wall carpet, In wall AC unit, two insulated slider windows (East and South) Pull down attic access and two ceiling fans. There is a 2'6" x 5' storage closet in the South West corner,

Room 2 is a storage/work shop measuring approx. 7'x12'

Propane inspection was completed 10/01/25 and Pest inspection completed 09/22/2

The lot inspections are done by amateur volunteers on the "Lot Improvement Committee."

They endeavor to do their best, but on occasion, things needing attention are missed. If for no other reason, we strongly recommend that prospective buyers visit the park and inspect the property personally. There are pictures of the lot available that we suggest you take advantage of at the bare minimum. Lot is being sold "As Is".

# **LOT IMPROVEMENT COMMITTEE PRE-TRANSFER INSPECTION**

	Page 1 of 3
	Current Leaseholder: Da Vi S
	LOT#: 10 DATE: 10/24/2025
ot	
•	Utility pedestal: worker accessible? Yes: No:
	o Tampered with? Yes: No: V
	O Breakers and receptacles in good condition? Yes: No: O Do all receptacles have power? Yes: No:
•	Park water supply line and hose bibbs in good condition? Yes: V No: No: No: No: No: Vo: Vo: No: Vo: Vo: No: Vo: Vo: No: Vo: Vo: Vo: Vo: No: Vo: Vo: Vo: No: Vo: Vo: No: Vo: Vo: Vo: Vo: Vo: Vo: Vo: Vo: Vo: V
•	Propane tank? Yes: No: Approved inspection should already be completed.
•	o Tank ad line condition? FOOD Trope of el
	o Propane tank capacity: 150
	o Propane amount left in tank:
	Lot Perimeter Fence? Yes: No: Material?
	o Condition?
	O Higher than four feet? Yes: No:
	o Item(s) attached to street perimeter fence? Yes: No: \
•	Trees/Shrubs/Plants? Yes: No: V
	Minimum five feet from lot lines and leach field to center of plants? Yes: No:
	O Do trees and/or plants interfere with traffic (visibility, height)? Yes: No:
	O Do trees and/or plants interfere with neighbor's fot use? Yes: No:
•	Leach field has a four-foot barrier from street? Yes: No:
	o Leach field unobstructed (four-feet wide and 30 feet long)? Yes: No:
•	Concrete parking pad? Yes: No: Concrete or stone walkways or patios? Yes: No: V
•	Total area of non-permeable ground coverage, including shed and original parking pad: 1266 sq.
•	Permanent structure behind the RV parking pad? Yes: No:
•	Clothesline? Yes: No: No: Retractable/fold up type? Yes: No:
_	
•	Antenna? Yes: No: Material: Condition: Lot Dividers? Yes: No: Material: Material: Kondition: Fair / Condition:
•	Lot Dividers? Yes: V No: Material: Imbers truckondition: Fair
	·

#### LOT IMPROVEMENT COMMITTEE PRE-TRANSFER INSPECTION

Page 2 of 3 Current Leaseholder: 2. Shed: Yes: No: Setback at least 30 feet from street? Yes: Minimum 3 feet from lot lines? Yes: V Foundation: Slab V Skids: Tied down with mobile home anchors? Yes: Pressure treated lumber? Yes: No: Side facing street maximum 24 feet in length? Yes: \ Shed exterior measurements, not including porch: 12 + 2Covered porch measurements: 8 X7 9.5 feet in length or less? Yes: > Roof material? Shrng/45 Condition? Eaves condition? +AIV Gutters? Yes: No: ✓ Condition? Exterior Wall Material? Hardy board Condition? o Dry Rot, Cracks, paint? Condition?\_ o Window and door moldings? Condition? Attic Access? Yes: V No: Type? (N) Jown addondition? Number of windows? \_\_ \_ Locations: @ast + west Interior Wall Covering Yesz No: Material? Shect volk panel Gondition? Ceiling Covering: Yes: V No: Material? Sheet rick Condition? Good Window and screen condition? Window treatments? Yes: No: Condition? Propane appliances in shed (heater, dryer)? Yes: / No: // Condition? Heater or air conditioner wall mounted? Yes: \( \sqrt{No}: Type:/xiV Condition? 2000 LP appliances have shut-off valves? Yes:\_\_\_\_ No:\_\_\_// Other appliances removed? Yes: V No: Single 20-amp electrical service? Yes: V No: / ○ Electrical service underground? Yes: ∨ No: ○ Electrical outlets, switches, lights, etc. working? Yes: V No: Water supplied to shed? Yes: No: V Supplied by hose from Bibb? Yes: No: Sinks, Faucets? Yes:\_\_\_ No: Condition? (V) Location? Shed water discharges into a French drain? Yes:\_\_\_\_\_ Personal items removed? Yes: \( \scale \) No: Comments (shed overall condition, extra features, added value):

### **LOT IMPROVEMENT COMMITTEE PRE-TRANSFER INSPECTION**

Page 3 of 3

Current Leaseholder: <u>Davis</u>
LOT#: 10 DATE: 10/24/2025
Site layout map on back if required
11. Maintenance, neglected. damaged Items requiring correction before transfer;  No backflow preventer Complete Brown Johnson 10/30
Romove trailer tre downs Complete Brod Jour 10/30
Report exterior on parch light complete Brul Joro 1/5
Report Soffits Complete Brul form 11/10
Remove wire perimeter day fence - complete Brail from 10/30
12. Bylaws/Standing Rules Violations to be noted and handled before transfer:
Inspected By Committee Members: 1:   Swal   Swal   Date   0   2025
2: SALM Date: 10/24/25 3: Rondy Ropen Date: 14/24/25

#### Disclaimer

This report was prepared by SKP Members, not professional real estate inspectors, therefore no warranties or guarantees are expressed or implied. This report is submitted as a record of our "good faith" observations of this shed and lot. It is not a substitute for the Prospective Member's personal inspection and evaluation of the shed and lot and is offered only to help a Prospective Member decide whether they wish to proceed. All measurements and observations are approximate. Prospective Member should personally visit this lot to determine its condition and suitability.